

BMW i3 Servicing & Repairs Fixed Price Menu (from 03/2026)

	REGULAR PRICE	LOYALTY PRICE*
--	---------------	----------------

* available exclusively to customers who purchased their i3 from Wisely

BIENNIAL FULL SERVICE

Comprehensive service and inspection due every 24 months, irrespective of mileage. All services include a microfilter and brake fluid change, 115 point inspection, road test, ISTA fault code analysis, 12V and HV battery health checks, appraisal of brakes & tyres, hinge greasing, fluid top ups, updating the service record in AOS/iDrive and resetting CBS indicator

BMW i3 / i3s	£234.84	£200.04
BMW i3 / i3s (with Range Extender oil service)	£366.79	£315.19

We only use **genuine BMW parts**, including: carbon-activated microfilters, brake fluid, screen wash, oil filters and engine oil

HIGH USE RANGE EXTENDER OIL CHANGE

Interim oil and oil filter change for cars where the Range Extender has ran for more than 200 hours / 10,000 miles since last oil change

using only genuine BMW oil filter, sump washer and engine oil	£155.95	£134.35
---	----------------	---------

PRE/POST PURCHASE INSPECTION

A comprehensive (non-servicing) i3 inspection which can be carried out pre / post vehicle purchase, or before the expiry of a warranty. Includes a 115 point inspection, road test, ISTA fault code analysis, 12V & HV battery health checks and an appraisal of brakes & tyres

	£138.00	£110.40
--	----------------	---------

BRAKES

Replace front brake pads (genuine BMW)	£214.23	£195.03
Replace front brake pads (OE Febi Bilstein)	£162.16	£142.96
Replace front brake discs and pads (genuine BMW)	£394.33	£367.93
Replace front brake discs and pads (OE Febi Bilstein)	£296.94	£270.54
Replace rear brake pads (genuine BMW)	£216.07	£194.47
Replace rear brake pads (OE Febi Bilstein)	£153.58	£131.98
Replace rear brake discs and pads (genuine BMW)	£347.21	£314.81
Replace rear brake discs and pads (OE Febi Bilstein)	£287.11	£254.71
Replace parking (hand)brake actuator	£110.28	£100.68

SUSPENSION

Disassemble front suspension struts & replace gaiters (both sides)	£224.35	£187.15
Disassemble front suspension strut & replace gaiter (one side)	£127.18	£105.58
+ replace top mount (surcharge per side)	£65.94	£65.94
+ replace coil spring (surcharge per side, OE equivalent)	from £49.82	£49.82
+ replace coil spring (surcharge per side, genuine BMW)	from £126.68	£126.68
+ replace front damper (surcharge per side, OE equivalent)	from £166.99	£162.19
+ replace front damper (surcharge per side, genuine BMW)	from £206.38	£201.58
Replace front wheel bearing, per side	£312.14	£294.14
Supply & fit Evolve coilover kit (dampers and springs)	£1,149.00	£1,080.82
Supply & fit Evolve coilover kit (dampers only)	£989.90	£921.72

... anti roll bar, drop link, bushes, track rod etc work also undertaken

Call for quote

MOTOR MOUNTS

The i3 motor (and REx) are suspended on brackets by 2 rubber mounts which can fail. Over the years, BMW upgraded both the bracketry and the size of the bolts, meaning on older cars it is not possible to just replace a failed mount, but also the bracketry.

Replace motor mount and bolt (per side)	£258.12	£234.12
Replace both motor mounts with upgraded bolts and metal bracketry (BEV)	£1,059.07	£967.87
Replace both motor mounts with upgraded bolts and metal bracketry (REx)	£1,044.58	£938.98

ELECTRICS





Replace and register 12v battery (genuine BMW)	£171.00	£156.60
Replace charging door actuator	£145.87	£136.27
Replace charging cable locking pin actuator	£169.87	£155.47
Repair door window lifter wiring harness (window not operating correctly)	£199.88	£161.48
+ replace window lifter motor (if found to be required during repair)	£156.59	£156.59
Repair broken wiring for seat belt clasp sensor (under seat)	£120.00	£96.00
Replace heated seat pad (turning off after a few seconds)	£415.81	£363.01
Replace driver's airbag module	from £990.44	£976.04
Replace low-temperature coolant pump	from £437.78	£408.98
Replace and code reversing camera (blurry/broken)	from £612.56	£564.56
Replace air quality (AUC) sensor	£137.81	£125.81
Resolve clogged washer jets	from £48.00	£38.40
Exchange HVAC panel (flickering LEDs, repaired part)	£216.00	£196.80

... headlights, bulbs, sunroof, TPMS, wing mirrors, PDC, reversing camera and general 12v work also undertaken

Call for quote

HIGH VOLTAGE ELECTRICS

Several part numbers exist for each HV component depending on a car's exact specification. Call for an exact quote

Replace auxiliary heater	£1,033.01	£1,001.81
Replace charging port & harness (BEV or REx, no CCS)	from £737.26	£677.26
Replace charging port & harness (BEV with CCS)	from £1,217.72	£1,145.72
Replace charging port & harness (REx with CCS)	from £1,337.72	£1,241.72
Replace cable from HV battery to EME	from £330.34	£291.94
Replace and code KLE (BEV)	from £1,816.61	£1,720.61
Replace and code KLE (REx)	from £1,968.74	£1,854.74
Replace and code EME (BEV)	from £4,856.16	£4,652.16 
Replace and code EME (REx)	from £5,237.50	£4,973.50 
Replace electric motor (BEV)	from £3,470.33	£3,254.33 
Replace electric motor (REx)	from £3,843.80	£3,555.80 


TRANSMISSION & DRIVE SHAFTS

Replace e-transmission (BEV)	£1,211.81	£1,121.81
Replace e-transmission (REx)	£2,485.26	£2,179.26 
Replace park lock actuator (BEV)	£259.02	£232.62
Replace park lock actuator (REx)	£499.02	£424.62
Change e-transmission oil	£262.55	£224.15
Replace drive shaft	from £463.74	£415.74

RANGE EXTENDER

Replace fuel pump relay	£41.59	£36.79	
Replace both injectors	£503.57	£467.57	
Replace both spark plugs	£224.86	£186.46	
Replace pre-cat oxygen sensor	£486.37	£450.37	
Replace post-cat oxygen sensor	£425.10	£389.10	
Fuel tank pressure sensor (recalibration only)	£36.00	£28.80	
Fuel tank pressure sensor (replacement)	£469.22	£409.22	
Replace fuel ventilation line	£196.07	£166.07	
Replace crankshaft position sensor	£1,464.77	£1,200.77	
Replace starter generator	£3,765.56	£3,477.56	

TRIM & BODY

Supply & fit matt Dark Oak wood dashboard trims	£306.52	£294.52	
Door seal replacement, per side	£202.88	£182.48	
Replace faulty door lock assembly	£426.35	£384.35	
Release & replace faulty door lock assembly (won't open either side)	£486.35	£432.35	
Replace tailgate (excl new badges and chrome accent bar if applicable)	£1,680.67	£1,596.67	
Replace tailgate gas struts (pair)	£185.38	£178.18	
Replace front centre undertray	£79.63	£73.63	
Replace front wiper blades (BMW)	£57.22	£57.22	
Replace front wiper blades (BOSCH)	£33.71	£33.71	
Replace rear wiper blade (BOSCH)	£15.08	£15.08	

... inner & outer door handle, door glass, window lifter, mirror housing repairs and general trim work also undertaken

Call for quote

OTHER / DIAGNOSIS

For any work/faults which are uncertain and do not fall within the above fixed price menu, an initial diagnosis session is required, with any work authorised thereafter attracting our hourly labour rate

Remote diagnosis session (RITA)	£45.00	£36.00	
Diagnosis session (1/2 hour)	£72.00	£57.60	
Hourly labour rate	£120.00	£96.00	

*All prices shown include VAT and sundry provisions for lubricants and other small consumables.
Extraction of stripped / sheared fasteners not included.*

DISCLAIMER: Prices are subject to daily changes and in some cases the exact pricing will depend on parts required for a given vehicle specification. Please check the final provided quote when booking.